

Summary
Total project issues : 55
Total printed issues : 54

Assigned to	All	Zones	All
Types	All	Phases	All
Priorities	All	Labels	All
Status	All	Issue group	All
Teams	All	Author	All
Numbers	All		


1.6 days

AVERAGE TIME TO CLOSE AN ISSUE


55.4 days

AVERAGE OPENED ISSUE AGE

TOTAL VS CLOSED ISSUES



ISSUES BY ASSIGNED TO




ISSUES BY PRIORITIES



ISSUES BY PHASES



ISSUES BY ZONES




ISSUES BY STATUS




ISSUES BY TYPE



ISSUES BY TEAMS




ISSUES BY GROUPS



47
7

ISSUES BY LABELS



9
27
1
2
18


ISSUES BY AUTHOR




1
47
1
3
2

688. Mezzanine floor extension**Description:**

The floor of the mezzanine is enlarged to create a reception area for the lift



Author	Vincent Bergeron (vincent.bergeron@bimone.com)
Created	1/26/2018 12:17 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	1/26/2018 12:00 AM
Assigned to	Jonas Claros Vasquez (jonas.claros@bimone.com)
Type	Issue
Priority	High
Status	Open
Zone	Mezz.
Phase	Design
Labels	Plumbing
Issue group	
Teams	Architect, Structural Engineer
Notification list	

COMMENTS**USER / DATE**


Jonas Claros Vasquez
1/26/2018 1:23 PM

COMMENTS

Les poutres sont ajustées.

686. New bathroom configuration**Description:**


New architectural layout, to be adapted to plumbing



Author	Vincent Bergeron (vincent.bergeron@bimone.com)
Created	1/26/2018 11:32 AM
Last changed by	Vincent Bergeron (vincent.bergeron@bimone.com)
Last changed	1/26/2018 2:01 PM
Due date	1/26/2018 12:00 AM
Assigned to	Maxime Sanschagrin (Maxime.sanschagrin@bimone.com)
Type	Issue
Priority	High
Status	Open
Zone	Mezz.
Phase	Design
Labels	Architecture, Electrical, Mechanical, Plumbing
Issue group	
Teams	Architect, MEP engineer
Notification list	

691. Missing roof - part II

Description: Add missing roofs for roof drains positionning.




Author	Maxime Sanschagrin (Maxime.sanschagrin@bimone.com)
Created	1/26/2018 1:02 PM
Last changed by	Mustapha Djaziri (mustapha.djaziri@bimone.com)
Last changed	1/26/2018 3:46 PM
Due date	1/26/2018 12:00 AM
Assigned to	Jonas Claros Vasquez (jonas.claros@bimone.com)
Type	Request
Priority	Medium
Status	Closed
Zone	Roof
Phase	Design
Labels	Architecture
Issue group	
Teams	Architect
Notification list	

COMMENTS

USER / DATE	COMMENTS
Mustapha Djaziri 1/26/2018 3:08 PM	retabli
Mustapha Djaziri 1/26/2018 3:08 PM	retabli

690. Missing roof

Description: Please add roof for roof drain positionning.




Author	Maxime Sanschagrin (Maxime.sanschagrin@bimone.com)
Created	1/26/2018 1:00 PM
Last changed by	Mustapha Djaziri (mustapha.djaziri@bimone.com)
Last changed	1/26/2018 3:47 PM
Due date	1/26/2018 12:00 AM
Assigned to	Jonas Claros Vasquez (jonas.claros@bimone.com)
Type	Request
Priority	Medium
Status	Closed
Zone	Roof
Phase	Design
Labels	Architecture
Issue group	
Teams	Architect
Notification list	

COMMENTS

USER / DATE	COMMENTS
Mustapha Djaziri 1/26/2018 3:09 PM	la porte requise un rehaussement en elevation de 200mm par rapport au surface de toit
Mustapha Djaziri 1/26/2018 3:09 PM	la porte requise un rehaussement en elevation de 200mm par rapport au surface de toit

689. Roof Opening


Description: What is this for?



Author	Maxime Sanschagrin (Maxime.sanschagrin@bimone.com)
Created	1/26/2018 12:59 PM
Last changed by	Maxime Sanschagrin (Maxime.sanschagrin@bimone.com)
Last changed	1/26/2018 12:59 PM
Due date	1/26/2018 12:00 AM
Assigned to	Mustapha Djaziri (mustapha.djaziri@bimone.com)
Type	Quality control
Priority	Medium
Status	Open
Zone	Roof
Phase	Design
Labels	Architecture
Issue group	
Teams	Architect
Notification list	


684. Information needed concerning the exterior walls

Description: Hi Mustafa, are the base of your walls sitting on the Beams or not? Please let me know ASAP.



Author	Jonas Claros Vasquez (jonas.claros@bimone.com)
Created	1/26/2018 10:39 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/2/2018 12:00 AM
Assigned to	Mustapha Djaziri (mustapha.djaziri@bimone.com)
Type	Issue
Priority	High
Status	Open
Zone	Ground Floor
Phase	Design
Labels	Plumbing
Issue group	
Teams	
Notification list	

COMMENTS



USER / DATE

Jonas Claros Vasquez
1/26/2018 10:40 AM

COMMENTS


USER / DATE

Carl Veillette
1/26/2018 10:43 AM

COMMENTS

Hey Jonas, what do you need exactly? Are you talking about the wall lateral alignment?

786. Beam.2.31 (W16X67)



Author	Carl Veillette (carl.veillette@bimone.com)
Created	9/23/2016 10:41 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/8/2018 12:01 PM
Due date	3/14/2018 8:00 PM
Assigned to	
Type	Comment
Priority	Critical
Status	Open
Zone	
Phase	Design
Labels	
Issue group	
Teams	
Notification list	

COMMENTS

USER / DATE

Carl
9/23/2016 10:41 AM


COMMENTS

779. Pl



Author	Carl Veillette (carl.veillette@bimone.com)
Created	3/7/2018 9:52 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/12/2018 10:24 AM
Due date	3/14/2018 2:51 PM
Assigned to	
Type	Issue
Priority	Low
Status	Resolved
Zone	
Phase	Design
Labels	
Issue group	
Teams	
Notification list	

756. Column spacing




Author	Carl Veillette (carl.veillette@bimone.com)
Created	3/2/2018 10:58 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/6/2018 11:52 PM
Due date	3/9/2018 12:00 AM
Assigned to	
Type	Issue
Priority	Low
Status	Open
Zone	
Phase	Design
Labels	Architecture
Issue group	
Teams	
Notification list	

753. New Group**Description:** Clash: Clash1

Clash Test: C-ARC-Ceilings vs STR

Clash: Clash2

Clash Test: C-ARC-Ceilings vs STR



Author	Carl Veillette (carl.veillette@bimone.com)
Created	2/23/2018 2:09 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/6/2018 11:52 PM
Due date	3/2/2018 12:00 AM
Assigned to	
Type	Issue
Priority	Low
Status	Closed
Zone	
Phase	Design
Labels	Architecture
Issue group	
Teams	
Notification list	

751. Clash7**Description:** Clash Test: H-PLM-Plumbing Fixture vs STR

Grid Location: Z-ZZ : Origin

Clash Elements

Item Path: File/File/CAR_DEALER-PLM_EXPORT.nwc/LEVEL 2/Plumbing Fixtures/M_Roof Drain/380 mm Strainer - 200 mm Drain/M_Roof Drain/380 mm Strainer - 200 mm Drain/Solid

Quick Properties

Item Name: 380 mm Strainer - 200 mm Drain

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_MEP_PLUM.rvt

Element ID Value: 1121292

Item Path: File/File/CAR_DEALER-SS_EXPORT.nwc/TOP OF HIGHER GROUND FLOOR/Structural Columns/HSS-Hollow Structural Section-Column/HSS8X8X3/8/HSS-Hollow Structural Section-Column/HSS8X8X3/8/Metal - Steel


Quick Properties

Item Name: Metal - Steel

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_SS_STR.rvt

Element ID Value: 2108401



Author	Carl Veillette (carl.veillette@bimone.com)
Created	2/15/2018 4:56 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/6/2018 11:52 PM
Due date	2/22/2018 12:00 AM
Assigned to	
Type	Clash
Priority	High
Status	Open
Zone	
Phase	Design
Labels	Architecture
Issue group	H-PLM-Plumbing Fixture vs STR
Teams	
Notification list	

750. Clash6**Description:** Clash Test: H-PLM-Plumbing Fixture vs STR

Grid Location: Z-ZZ : Origin

Clash Elements

Item Path: File/File/CAR_DEALER-PLM_EXPORT.nwc/Top of Steel - Roof/Plumbing Fixtures/M_Roof Drain/380 mm Strainer - 200 mm Drain/M_Roof Drain/380 mm Strainer - 200 mm Drain/Solid

Quick Properties

Item Name: 380 mm Strainer - 200 mm Drain

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_MEP_PLUM.rvt

Element ID Value: 1121292

Item Path: File/File/CAR_DEALER-SS_EXPORT.nwc/TOS Roof/Structural Framing/M_CISC_Standard-Canam-Joist-Defined/Joist 700/M_CISC_Standard-Canam-Joist-Defined/Joist 700/Metal - Steel


Quick Properties

Item Name: Metal - Steel

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_SS_STR.rvt

Element ID Value: 2336654



Author	Carl Veillette (carl.veillette@bimone.com)
Created	2/15/2018 4:56 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/6/2018 11:52 PM
Due date	2/22/2018 12:00 AM
Assigned to	
Type	Clash
Priority	High
Status	Open
Zone	
Phase	Design
Labels	Architecture
Issue group	H-PLM-Plumbing Fixture vs STR
Teams	
Notification list	

749. Clash5**Description:** Clash Test: H-PLM-Plumbing Fixture vs STR

Grid Location: Z-ZZ : Origin

Clash Elements

Item Path: File/File/CAR_DEALER-PLM_EXPORT.nwc/Top of Steel - Roof/Plumbing Fixtures/M_Roof Drain/380 mm Strainer - 200 mm Drain/M_Roof Drain/380 mm Strainer - 200 mm Drain/Solid

Quick Properties

Item Name: 380 mm Strainer - 200 mm Drain

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_MEP_PLUM.rvt

Element ID Value: 1121292

Item Path: File/File/CAR_DEALER-SS_EXPORT.nwc/TOS Roof/Structural Framing/M_CISC_Standard-Canam-Joist-Defined/Joist 700/M_CISC_Standard-Canam-Joist-Defined/Joist 700/Metal - Steel


Quick Properties

Item Name: Metal - Steel

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_SS_STR.rvt

Element ID Value: 2333787



Author	Carl Veillette (carl.veillette@bimone.com)
Created	2/15/2018 4:56 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/12/2018 10:00 AM
Due date	2/22/2018 12:00 AM
Assigned to	
Type	Clash
Priority	High
Status	Open
Zone	
Phase	Design
Labels	Architecture
Issue group	H-PLM-Plumbing Fixture vs STR
Teams	
Notification list	

748. Clash4

Description: Clash Test: H-PLM-Plumbing Fixture vs STR

Grid Location: Z-ZZ : Origin

Clash Elements

Item Path: File/File/CAR_DEALER-PLM_EXPORT.nwc/Top of Steel - Roof/Plumbing Fixtures/M_Roof Drain/380 mm Strainer - 200 mm Drain/M_Roof Drain/380 mm Strainer - 200 mm Drain/Solid

Quick Properties

Item Name: 380 mm Strainer - 200 mm Drain

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_MEP_PLUM.rvt

Element ID Value: 1121292

Item Path: File/File/CAR_DEALER-SS_EXPORT.nwc/TOS Roof/Structural Framing/M_CISC_Standard-Canam-Joist-Defined/Joist 700/M_CISC_Standard-Canam-Joist-Defined/Joist 700/Metal - Steel


Quick Properties

Item Name: Metal - Steel

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_SS_STR.rvt

Element ID Value: 2336654



Author	Carl Veillette (carl.veillette@bimone.com)
Created	2/15/2018 4:56 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/6/2018 11:52 PM
Due date	2/22/2018 12:00 AM
Assigned to	
Type	Clash
Priority	High
Status	Open
Zone	
Phase	Design
Labels	Architecture
Issue group	H-PLM-Plumbing Fixture vs STR
Teams	
Notification list	

747. Clash3

Description: Clash Test: H-PLM-Plumbing Fixture vs STR

Grid Location: Z-ZZ : Origin

Clash Elements

Item Path: File/File/CAR_DEALER-PLM_EXPORT.nwc/LEVEL 2/Plumbing Fixtures/M_Roof Drain/380 mm Strainer - 200 mm Drain/M_Roof Drain/380 mm Strainer - 200 mm Drain/Solid

Quick Properties

Item Name: 380 mm Strainer - 200 mm Drain

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_MEP_PLUM.rvt

Element ID Value: 1121292

Item Path: File/File/CAR_DEALER-SS_EXPORT.nwc/TOS Roof/Structural Framing/M_CISC_Standard-Canam-Joist-Defined/Joist 700/M_CISC_Standard-Canam-Joist-Defined/Joist 700/Metal - Steel


Quick Properties

Item Name: Metal - Steel

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_SS_STR.rvt

Element ID Value: 2332817



Author	Carl Veillette (carl.veillette@bimone.com)
Created	2/15/2018 4:56 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	2/15/2018 4:56 PM
Due date	2/22/2018 12:00 AM
Assigned to	
Type	Clash
Priority	High
Status	Open
Zone	
Phase	Design
Labels	
Issue group	H-PLM-Plumbing Fixture vs STR
Teams	
Notification list	

746. Clash2**Description:** Clash Test: H-PLM-Plumbing Fixture vs STR

Grid Location: Z-ZZ : Origin

Clash Elements

Item Path: File/File/CAR_DEALER-PLM_EXPORT.nwc/Top of Steel - Roof/Plumbing Fixtures/M_Roof Drain/380 mm Strainer - 200 mm Drain/M_Roof Drain/380 mm Strainer - 200 mm Drain/Solid

Quick Properties

Item Name: 380 mm Strainer - 200 mm Drain

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_MEP_PLUM.rvt

Element ID Value: 1121292

Item Path: File/File/CAR_DEALER-SS_EXPORT.nwc/TOS Roof/Structural Framing/M_CISC_Standard-Canam-Joist-Defined/Joist 700/M_CISC_Standard-Canam-Joist-Defined/Joist 700/Metal - Steel


Quick Properties

Item Name: Metal - Steel

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_SS_STR.rvt

Element ID Value: 2334519



Author	Carl Veillette (carl.veillette@bimone.com)
Created	2/15/2018 4:56 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	2/15/2018 4:56 PM
Due date	2/22/2018 12:00 AM
Assigned to	
Type	Clash
Priority	High
Status	Open
Zone	
Phase	Design
Labels	
Issue group	H-PLM-Plumbing Fixture vs STR
Teams	
Notification list	

745. Clash1**Description:** Clash Test: H-PLM-Plumbing Fixture vs STR

Grid Location: Z-ZZ : Origin

Clash Elements

Item Path: File/File/CAR_DEALER-PLM_EXPORT.nwc/Top of Steel - Roof/Plumbing Fixtures/M_Roof Drain/380 mm Strainer - 200 mm Drain/M_Roof Drain/380 mm Strainer - 200 mm Drain/Solid

Quick Properties

Item Name: 380 mm Strainer - 200 mm Drain

Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_MEP_PLUM.rvt

Element ID Value: 1121292

Item Path: File/File/CAR_DEALER-SS_EXPORT.nwc/TOS Roof/Structural Framing/M_CISC_Standard-Canam-Joist-Defined/Joist 700/M_CISC_Standard-Canam-Joist-Defined/Joist 700/Metal - Steel


Quick Properties

Item Name: Metal - Steel


Item Type: Solid

Item Source File Name: BIM 360://Car Dealer 2018/BIM1_AUTOP_SS_STR.rvt


Element ID Value: 2334641



Author	Carl Veillette (carl.veillette@bimone.com)
Created	2/15/2018 4:56 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	2/15/2018 4:56 PM
Due date	2/22/2018 12:00 AM
Assigned to	
Type	Clash
Priority	High
Status	Open
Zone	
Phase	Design
Labels	
Issue group	H-PLM-Plumbing Fixture vs STR
Teams	
Notification list	

724. Beam issue.

Author	Carl Veillette (carl.veillette@bimone.com)
Created	2/12/2018 6:32 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	2/12/2018 6:32 PM
Due date	2/18/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Critical
Status	Closed
Zone	
Phase	Design
Labels	
Issue group	
Teams	
Notification list	

COMMENTS**USER / DATE**

CarlVeillette
2/12/2018 6:30 PM

COMMENTS

Change beam connection type.


USER / DATE

CarlVeillette
2/12/2018 6:31 PM

COMMENTS


Verify connections at both ends.

723. Check beam connection.



Author	Carl Veillette (carl.veillette@bimone.com)
Created	2/12/2018 6:32 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	2/12/2018 6:32 PM
Due date	2/18/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Critical
Status	Closed
Zone	
Phase	Design
Labels	
Issue group	
Teams	
Notification list	

COMMENTS



USER / DATE

CarlVeillette
2/12/2018 6:27 PM

COMMENTS

Check beam connection.

USER / DATE


CarlVeillette
2/12/2018 6:27 PM

COMMENTS

Beam size to be changed.

722. Check duct alignment in webs

Description: Ducts must be aligned in the joists webs.



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/27/2018 11:36 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/3/2018 11:36 PM
Assigned to	Maxime Sanschagrin (Maxime.sanschagrin@bimone.com)
Type	Issue
Priority	Critical
Status	Open
Zone	Mezz.
Phase	Design
Labels	Plumbing
Issue group	
Teams	
Notification list	

COMMENTS


USER / DATE

Carl Veillette
3/1/2018 11:48 AM

COMMENTS


Hi all, just doing a quick follow up on this.

713. Align stud walls




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 4:35 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/2/2018 4:35 PM
Assigned to	
Type	Issue
Priority	Medium
Status	Open
Zone	
Phase	Design
Labels	Plumbing
Issue group	
Teams	
Notification list	

703. Concrete slab missing in the elevator




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 3:28 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/26/2018 3:43 PM
Due date	2/2/2018 3:28 PM
Assigned to	
Type	Issue
Priority	Low
Status	Open
Zone	Basement
Phase	Design
Labels	
Issue group	
Teams	
Notification list	

702. Check lateral stud wall alignment




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 3:26 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/2/2018 3:26 PM
Assigned to	Arthur Grenier (arthur.grenier@bimone.com)
Type	Issue
Priority	Medium
Status	Open
Zone	Roof
Phase	Design
Labels	Plumbing
Issue group	
Teams	
Notification list	

701. Check stud wall height




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 3:25 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/2/2018 3:25 PM
Assigned to	Jonas Claros Vasquez (jonas.claros@bimone.com)
Type	Issue
Priority	Medium
Status	Open
Zone	Roof
Phase	Design
Labels	Plumbing
Issue group	
Teams	
Notification list	

700. Check curtain wall lintel




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 3:22 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/2/2018 3:22 PM
Assigned to	Jonas Claros Vasquez (jonas.claros@bimone.com)
Type	Issue
Priority	High
Status	Open
Zone	Ground Floor
Phase	Design
Labels	Plumbing
Issue group	
Teams	
Notification list	

696. Check those beams connections




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 2:58 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/2/2018 2:58 PM
Assigned to	
Type	Issue
Priority	Critical
Status	Open
Zone	Mezz.
Phase	Design
Labels	Plumbing
Issue group	
Teams	
Notification list	

695. These should be stud walls



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 2:56 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/2/2018 2:56 PM
Assigned to	
Type	Issue
Priority	Low
Status	Open
Zone	Ground Floor
Phase	Design
Labels	Plumbing
Issue group	
Teams	
Notification list	

694. Remove parking lines from architecture model



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 2:18 PM
Last changed by	Arthur Grenier (arthur.grenier@bimone.com)
Last changed	1/26/2018 4:48 PM
Due date	2/2/2018 2:18 PM
Assigned to	Arthur Grenier (arthur.grenier@bimone.com)
Type	Request
Priority	Low
Status	Closed
Zone	Site
Phase	Design
Labels	Architecture
Issue group	
Teams	
Notification list	

COMMENTS


USER / DATE

Arthur Grenier
1/26/2018 2:31 PM

COMMENTS


Parkings removed. Extra curb and plants as well

693. Check wall top elevation




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 2:17 PM
Last changed by	Mustapha Djaziri (mustapha.djaziri@bimone.com)
Last changed	1/26/2018 4:06 PM
Due date	2/2/2018 2:17 PM
Assigned to	
Type	Issue
Priority	Medium
Status	Closed
Zone	Roof
Phase	Design
Labels	Architecture
Issue group	
Teams	
Notification list	

692. Curtain wall missing



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 2:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/26/2018 2:16 PM
Due date	2/2/2018 2:16 PM
Assigned to	
Type	Request
Priority	High
Status	Open
Zone	Ground Floor
Phase	Design
Labels	Architecture
Issue group	
Teams	
Notification list	

685. Check wall joins



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 10:48 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/26/2018 10:48 AM
Due date	2/2/2018 10:48 AM
Assigned to	
Type	Issue
Priority	Low
Status	Open
Zone	
Phase	Design
Labels	
Issue group	
Teams	
Notification list	

COMMENTS

USER / DATE


Carl Veillette
1/26/2018 10:48 AM

COMMENTS

Check wall joins

683. Verify notch in column

Description: Verify noth in column



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 8:20 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/1/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Closed
Zone	
Phase	
Labels	Plumbing
Issue group	
Teams	
Notification list	

COMMENTS

USER / DATE


Carl Veillette
1/26/2018 10:44 AM

COMMENTS

Is that issue closed?

682. Facade needs to be aligned.


Description: There is a space between the siding and the stud walls. Check id that spacing is required.



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 8:20 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/1/2018 7:00 PM
Assigned to	Mustapha Djaziri (mustapha.djaziri@bimone.com)
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Plumbing
Issue group	
Teams	
Notification list	

681. Doors missing

Description: Il manque une porte pour l'ascenseur et une porte piéton




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 8:20 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/1/2018 7:00 PM
Assigned to	Mustapha Djaziri (mustapha.djaziri@bimone.com)
Type	Comment
Priority	High
Status	Closed
Zone	
Phase	
Labels	Plumbing
Issue group	
Teams	
Notification list	

COMMENTS

USER / DATE	COMMENTS
Carl Veillette 1/26/2018 10:45 AM	Looks like the door are still missing. Are you guys working on that?
Carl Veillette 1/26/2018 10:45 AM	Looks like the door are still missing. Are you guys working on that?

680. Duplicated walls




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 8:20 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	2/1/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Plumbing
Issue group	
Teams	
Notification list	

COMMENTS


USER / DATE	COMMENTS
Jonas Claros Vasquez 1/26/2018 1:34 PM	The second wall has been deleted!

678. Topo level




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 8:20 AM
Last changed by	Mustapha Djaziri (mustapha.djaziri@bimone.com)
Last changed	1/26/2018 4:32 PM
Due date	2/1/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Closed
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	

677. Wall profile




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 8:20 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/27/2018 10:43 PM
Due date	2/1/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Critical
Status	Open
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	

676. Paring lots duplicated




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 8:20 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/27/2018 10:42 PM
Due date	2/1/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Low
Status	Closed
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	

675. Check topography bounding limits



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 8:20 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/27/2018 4:48 PM
Due date	2/1/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	


674. Add the car lifts




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 8:20 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/27/2018 4:50 PM
Due date	2/1/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	

673. Check door opening

Description: There is a door missing as well as the topo which is badly cut.



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/26/2018 8:20 AM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/27/2018 10:41 PM
Due date	2/1/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	

672. Revise rebars


Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Plumbing
Issue group	
Teams	
Notification list	

671. Check lobby dimensions

Description: À réviser




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/27/2018 4:47 PM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Closed
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	

669. Check space usage

Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/27/2018 4:45 PM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	

666. Ceiling extents

Description: Adjust ceiling extents.




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/27/2018 10:39 PM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	High
Status	Open
Zone	Ground Floor
Phase	Design
Labels	Architecture
Issue group	
Teams	
Notification list	

665. Railing missing

Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/26/2018 11:13 AM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	

664. Manhole


Description: Déplacer dans maquette de site



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/27/2018 10:38 PM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Low
Status	Closed
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	

663. Curtain wall and slab

Description: They are clashing. Please adjust slab edge and curtain wall height.



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Closed
Zone	
Phase	
Labels	Plumbing
Issue group	
Teams	
Notification list	


COMMENTS

USER / DATE

Jonas Claros Vasquez
1/26/2018 2:30 PM


COMMENTS

The architectural team adjusted the bottom of the exterior wall.

662. Soffit missing


Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/26/2018 11:13 AM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	

661. Missing curtain walls



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/26/2018 11:12 AM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	


660. Logo location



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/26/2018 8:29 AM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Architecture
Issue group	
Teams	
Notification list	


659. Weird wall

Description: What is the purpose of this wall.




Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Open
Zone	
Phase	
Labels	Plumbing
Issue group	
Teams	
Notification list	

658. Replace open web steel joist families



Author	Carl Veillette (carl.veillette@bimone.com)
Created	1/24/2018 11:16 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	3/13/2018 12:54 AM
Due date	1/31/2018 7:00 PM
Assigned to	
Type	Comment
Priority	Medium
Status	Closed
Zone	
Phase	
Labels	Plumbing
Issue group	
Teams	
Notification list	

COMMENTS




USER / DATE

Jonas Claros Vasquez
1/26/2018 1:58 PM

COMMENTS

Joist has been replaced for the ones with web.

697. Issue not coordinated



Author	Alexandre Cantin (alexandre.cantin@bimone.com)
Created	1/26/2018 3:10 PM
Last changed by	Carl Veillette (carl.veillette@bimone.com)
Last changed	1/26/2018 3:14 PM
Due date	2/2/2018 12:00 AM
Assigned to	Vincent GUEGUEN (vincent.gueguen@bimone.com)
Type	Issue
Priority	Low
Status	Open
Zone	
Phase	Design
Labels	Mechanical
Issue group	
Teams	
Notification list	